PTO/SB/44 (04-05)

Page __1__ of __1_

Approved for use through 04/30/2007, OMB 0651-0033 U.S. Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE

U.S. Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE
Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.
(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENTNO. : 7,		7,038,162 B2
APPLICATION NO.: 1(NO.:	10/713,759
SSUE DATE : M	:	May 2, 2006
NVENTOR(S) : B		

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent

Column 8, line 23, "filter" should be changed to --filler--;
Column 10. line 17, "trough" should be changed to --through--,

MAILING ADDRESS OF SENDER (Please do not use customer number below):

Ingrassia Fisher & Lorenz 7150 E. Camelback Rd., Suite 325 Scottsdale, Arizona 85251

is hereby corrected as shown below:

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentially is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is either to late 1.0 hour to complete, including gathering, preparing, and submitting the completed application from to the USPTO. Time will vary depending upon the individual case. Any contents on the amount of time you require to complete this form and/or suggestions for reducing this better, and the content of the complete of

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re U. S. Patent: 7,038,162 B2 Examiner: G. Evans

Issued: May 2, 2006 Group: 1725

Inventor(s): Baker et al. Docket No. H0005486

For: HAND-HELD LASER WELDING WAND FILLER MEDIA DELIVERY SYSTEMS AND

METHODS

CERTIFICATE OF CORRECTION UNDER 37 CFR 1.322

Attn: Certificate of Corrections Branch P.O. Box 1450 Alexandria, VA 22313-1450

Sir

Please correct the above-identified patent by issuing a Certificate of Correction for a Patent Office mistake under Rule 1.322 as follows:

Column 8, line 23, "filter" should be changed to --filler--; Column 10, line 17, "trough" should be changed to --through--.

These errors occurred through the fault of the Patent Office and no fee is involved. The issuance of a Certificate of Correction under Rule 1.322 is therefore considered proper.

Respectfully submitted,

Date: February 7, 2007 Ingrassia Fisher & Lorenz, P.C. /PAULD.AMROZOWICZ/ By: Paul D. Amrozowicz Attorney for Applicant(s) Reg. No. 45,264 Tel. (480) 385-5060